

SUBJECT: Condensate Control

EFFECTIVE DATE: September 2002 **REVISED:** July 2004

INTERPRETATION NUMBER: ADM – 3.0310.2

SEE ALSO: 2000 UMC – Section 310.2

INTERPRETATION SUMMARY

As an approved alternate to providing secondary overflow condensate drainage, this Department will approve the use of floatation switches that will deactivate the unit if the primary drains become clogged.